




| Parts List |     |             |                        |
|------------|-----|-------------|------------------------|
| ITEM       | QTY | PART NUMBER | DESCRIPTION            |
| 1          | 1   | DM10255SS   | 1" DRY MATE BALL       |
| 2          | 1   | RK1005      | REPAIR KIT PACK 1"     |
| 2-1        | 1   | DM10258     | 1" Drymate Teflon Seat |
| 2-2        | 1   | VSS10060    | 1" SS Thrust Washer    |
| 2-3        | 1   | VSS10160F   | Female Stem Packing    |
| 2-4        | 1   | VSS10160M   | Male Stem Packing      |
| 2-5        | 1   | VSS10204    | 1" SS Body Gasket      |
| 2-6        | 1   | VSS10258    | 1" SS Valve Seat       |



THIS DRAWING AND ALL INFORMATION CONTAINED THEREON ARE THE EXCLUSIVE PROPERTY OF BANJO CORPORATION.

UNLESS SPECIFICALLY NOTED, THIS DRAWING AND ITEMS SHOWN ON THIS DRAWING ARE SUBJECT TO CHANGE AT ANY TIME.



**BANJO CORPORATION**  
 150 BANJO DRIVE, CRAWFORDSVILLE, IN 47933  
 WEB SITE: WWW.BANJOCORP.COM  
 E-MAIL: BANJOSALES@IDEXCORP.COM

|             |                                |
|-------------|--------------------------------|
| DESCRIPTION | 1" SS MALE DRY MATE REPAIR KIT |
| PART NUMBER | DM101SS                        |

