


Parts List			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	12099	7/16-14 X 1 1/4" HHCS
2	1	12705BN	PUMP CHECKVALVE, BUNA
3	1	12772	IMPELLER
4	1	RK1002P	O-RING KIT
4-2	1	12713BN	MECHANICAL SEAL ASSY
4-3	1	12716	PUMP SLINGER
4-4	4	12717BN	#11 O'RING, BUNA
4-5	1	12719ABN	#375 O'RING, BUNA
4-6	1	12754BN	O'RING SEGMENT
4-7	1	A204BN	#204 O'RING, BUNA
5	2	UV15163BN	#114 O'RING, BUNA

THIS DRAWING AND ALL INFORMATION CONTAINED THEREON ARE THE EXCLUSIVE PROPERTY OF BANJO CORPORATION.

UNLESS SPECIFICALLY NOTED, THIS DRAWING AND ITEMS SHOWN ON THIS DRAWING ARE SUBJECT TO CHANGE AT ANY TIME.



BANJO CORPORATION

150 BANJO DRIVE, CRAWFORDSVILLE, IN 47933
 WEB SITE: WWW.BANJOCORP.COM
 E-MAIL: BANJOSALES@IDEXCORP.COM

DESCRIPTION	2" BUNA PUMP REPAIR KIT-5 VANE
PART NUMBER	12000ABN