

4



3

2

1

PARTS LIST

ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	17006	ADAPTER SHAFT
2	1	17008	PUMP IMPELLER
3	1	17011	WEAR PLATE
4	1	17018	PUMP ADAPTER GASKET
5	1	17035	MECH. SEAL ASSY.
6	2	17130	5/16-18 X 1" FHSCS



BANJO CORPORATION

150 BANJO DRIVE, CRAWFORDSVILLE, IN 47933
WEB SITE: WWW.BANJOCORP.COM
E-MAIL: BANJOSALES@IDEXCORP.COM

DESCRIPTION

REPAIR KIT FOR CAST IRON PUMP

PART NUMBER

17100

THIS DRAWING AND ALL INFORMATION CONTAINED THEREON ARE THE EXCLUSIVE PROPERTY OF BANJO CORPORATION.

UNLESS SPECIFICALLY NOTED, THIS DRAWING AND ITEMS SHOWN ON THIS DRAWING ARE SUBJECT TO CHANGE AT ANY TIME.

B

B

A

A

4

3

2

1

